Report No.: 8003-08-0

Work Assignment No.: 019-2JZZ

Contract No.: 68-W9-0051 September 15, 1992

Updated: December 8, 1992

Sandra Foose U.S. Environmental Protection Agency (USEPA) Region II Edison, New Jersey 08837

RE: Flags, Inc. Site Inspection Prioritization Letter Report

Dear Ms. Foose:

This correspondence provides a description of the Flags, Inc. (a.k.a Amko Manufacturing, Inc.) site (U.S. Environmental Protection Agency (USEPA) I.D. No. NJD002352300) located at 41 Oak Ave., in Bellmawr, Camden County, New Jersey.

Flags, Inc. is an active facility located on approximately two acres of land in a mixed commercial/residential area. During the period between 1945 to 1985 Flags, Inc. manufactured metal surgical instruments. As part of this process, a vapor degreaser was used for cleaning and drying metal parts. In addition, trichloroethylene and the acids (nitric, sulfuric, and muriatic) were used for pickling and cleaning of metal parts. For a period of 40 years, Flags, Inc. had been disposing of between one quart and one gallon per year of semi-liquid residue from their degreasing operations onto the ground surface outside the facility. This residue consisted of fibers from the polishing wheels, polish, and oils. The site documentation indicates inspections conducted by the New Jersey Department of Environmental Protection and Energy (NJDEPE) between 1983 and 1986 during which violations noted included the improper disposal of waste, and the unpermitted discharge of non-contact cooling water into an unlined drainage ditch, located along the southern perimeter of the site, without a New Jersey Discharge Elimination System (NJPDES) permit. Flags, Inc. was notified of the violations, and ordered to immediately correct them. By 1984, the residue was no longer being disposed of onto the ground. Instead, the residue was placed in a well-ventilated room, allowed to dry, and disposed of with the facility's non-hazardous solid waste. The unpermitted discharge of non-contact cooling water was discontinued by 1985.

In 1985, six soil samples were collected in compliance with the Environmental Cleanup Responsibility Act (ECRA) guidelines from the former disposal area, and from the unlined ditch which received non-contact cooling water. All samples were analyzed for volatile organic compounds, and only tetrachloroethylene was detected. As a result of this sampling, approximately 1.5 cubic yards of soil was excavated from the former disposal area. The area was backfilled with clean sand, and the soil removed off-site to an approved waste facility. Subsequently, NJDEPE approved a Negative Declaration calling for no further remedial action at the Flags, Inc. facility on July 10, 1985.

An EPA site inspection report was completed for the Flags, Inc. Site in 1991. Ten on-site soil samples were collected during the site inspection from the southern and western portions of the property at depths ranging from zero to seventy-two inches. All samples were analyzed and validated through the USEPA Contract Laboratory Program (CLP), and sample analysis indicated the presence of inorganic constituents. A reference soil sample from an area free of influence by past activities was not collected.

The screening score for the Flags, Inc. site is 11.84. A defined area of suspected soil contamination was indicated as the waste source for the Flags, Inc. site. This area was defined through soil sampling that indicated the presence of several inorganic contaminants in on-site soils.

The score for the groundwater migration pathway is 19.88. The Flags, Inc. site overlies four geologic units

Sandra Foose
U.S. Environmental Protection Agency

September 15, 1992 - Page 2 Updated: December 8, 1992

that consist of (in descending order of depth) the Englishtown Formation, the Woodbury Clay, the Merchantville Formation, and the Potamac-Raritan-Magothy (PRM) aquifer. The site is situated over the outcrop area of the Englishtown Formation. This unit consists of a massive dark-colored silty sand that is approximately forty feet thick. It reportedly contains a west to east groundwater flow at a depth of approximately 30 feet. Underlying the Englishtown Formation is the Woodbury Clay. This strata is composed of grayish-black massive micaceous clayey silt, and is approximately one hundred feet thick. The next lowest unit is the Merchantville Formation which is composed of dark gray to grayish-black micaceous clay to clayey silt with beds and lenses of glauconite sand which become more prominent near the top of the formation. The thickness of this unit is approximately fifty feet. Together, the Merchantville Formation and the Woodbury Clay act as a confining unit, however the lensing sand at the top of the Merchantville Formation may be tapped for potable water near the outcrop area. Underlying the Merchantville Formation is the PRM aquifer system, the most productive system in Camden county. This aquifer consists of sand with some gravel and is separated into three hydrogeologic units; the upper, the middle, and the lower, by confining units consisting of silts and clays. The total thickness for this system is approximately 400 feet.

Report No.: 8003-080

Within four miles of the site, groundwater is used extensively as a source of drinking water. Thirty-nine public supply wells from various water departments have been identified within a 4-mile radius of the Flags, Inc. site. Documentation indicates that thirty-seven of the wells draw from the lower PRM aquifer, and two of the wells tap the middle PRM aquifer. However, the presence of the abovementioned confining layers overlying these aquifers result in a low potential for contaminant migration to these municipal supply wells. The nearest well (screened in the lower PRM aquifer) is owned by the New Jersey American Water Company and is located approximately 0.57 miles north of the site. The total service population within four miles of the site is 123,227 people (0 - 0.25 mile, 0 people; 0.25 - 0.50 mile, 0 people; 0.50 - 1 mile, 14,317 people; 1 - 2 mile, 42,985 people; 2 - 3 mile, 39,410 people; 3 - 4 mile, 26,515 people). The proximity of the site to a wellhead protection area cannot be determined, pending promulgation by the NJDEPE of protected areas.

The score for the surface water pathway is 0.21. Stormwater and potential site-derived liquid material if spilled, would drain by overland flow to the Little Timber Creek which is located approximately 1,100 feet north of the site. The Little Timber Creek flows west to a confluence with the Delaware River which supports a bass population, and a New Jersey state endangered species. National Wetland Inventory (NWI) Maps and the U.S.G.S. Topographic Quadrangle for the surface water pathway indicate the presence of one-tenth of a mile of wetland frontage along Little Timber Creek, and sixteen miles of wetland frontage along the Delaware River. These wetlands consist of riverine tidal flats. The drinking water threat is of low potential concern as no surface water intakes are located within the target distance limit.

The score for the soil exposure pathway is 12.86. Although inorganic contaminants have been detected in surficial (0-2 feet) soil samples, there are no schools or day care facilities within 200 feet of the site. In addition, no documentation exists indicating the presence of contamination on nearby residential properties. The site is active with approximately three on-site workers. No known terrestrial sensitive environments are located on areas of suspected soil contamination.

The score for the air migration pathway is 0.48. Available documentation does not indicate a release to air from the site. Additionally, the only remaining waste source on-site is contaminated soil containing inorganic constituents with low air mobilities. Two acres of wetlands have been identified within a 1/2 mile radius of the Flags, Inc. site. Finally, there are approximately 197,936 people living within four miles of the site. This information does not support a significant air component score.

Sandra Foose U.S. Environmental Protection Agency September 15, 1992 - Page 3 Updated: December 8, 1992

Report No.: 8003-080

In summary, the lack of a significant waste source, combined with the characteristics of the underlying geology of the site, result in an overall score of 11.84. Therefore, the recommendation given for the above facility, based on background information gathered, is SITE EVALUATION ACCOMPLISHED (SEA). The following is the definition of SEA: To the best of the EPA's knowledge, Superfund has completed an assessment at this site, and has determined that no further steps to list this site on the NPL will be taken unless information indicating that this decision was not appropriate or other considerations make a recommendation for listing appropriate at a later time. A "SEA" decision does not necessarily mean that there is no hazard associated with a given site; it means only that based upon available information, the location is not judged to be a potential NPL site.

If you have any questions concerning the above, do not hesitate to call me at (609)-860-0100.

Sincerely,

LISA SZEGEDÍ SITE MANAGER

JOHN D. RIECKHOFF

PRE-REMEDIAL PROGRAM MANAGER

DENNIS STAINKEN, Ph.D.

WORK ASSIGNMENT MANAGER

To: File **Date:** August 10, 1992 From: Lisa Szegedi Project #: 8003-080 **Subject:** Drinking Water Sources Site Name: Flags, Inc. Within 4 miles of the site there are the following towns with the following sources of drinking water. 1) Bellmawr Twp.-Bellmawr Twp. obtains their drinking water from 4 wells which all pump at approximately the same level. 2 of the wells are located in the 1/2-1 mile ring while 2 of the wells are located in the 1-2 mile ring. The total service population is 9,522 people. Both wells located in the 1/2-1 mile ring tap the lower P-R-M aquifer while both of the wells located in the 1-2 mile ring tap the middle P-R-M aquifer. Therefore, 1/2-1 mile ring Lower aquifer 4,761 people served 1-2 mile ring Middle aquifer 4,761 people served 2) Brooklawn Twp.-Brooklawn Twp. obtains their drinking water from 3 wells which all pump at approximately the same level. All 3 of the well are located in the 2-3 mile ring and the total service population is 2,520 people. All of the wells tap the lower P-R-M aquifer. 3) Westville Twp.-Westville Twp. obtains their drinking water from 3 wells which all pump at approximately the same level. All 3 of the wells are located in the 2-3 mile ring, and the total service population is 7,000 people. All of the wells tap the lower P-R-M aguifer. 4) Deptford Twp.-Deptford Twp. obtains their drinking water from 6 wells which all pump at approximately the same level. Only 1 of the wells is located within 4 miles of the site, and it is located in the 2-3 mile ring. The total service population is 29,000 people. Therefore, 2-3 mile ring, 4,834 people served. Based on well depth it is assumed this well taps the lower P-R-M aquifer. 5) Collingswood Twp.-Collingswood Twp. obtains their drinking water from 7 wells which all pump approximately the same level. 2 of the wells are located in the 2-3 mile ring, and 5 wells are located in the 3-4 mile ring. The total service population is 21,000 people. Therefore, 2-3 mile ring, 6,000 people served, and 3-4 mile ring, 15,000 people served. All of the wells tap the lower P-R-M aguifer.

To. 5%		Date: A
To: File		Date: August 10, 1992
From: Lisa Szege		Project #: 8003-080
Subject: Drinking	Water Sources	Site Name: Flags, Inc.
(a.a., it)		
(con't)		
6) Haddonfield Twp.	-Haddonfield Twn, obtai	ns their drinking water from 4 wells which all pump at a
		Is are located in the 3-4 mile ring, and the total
		he wells tap the lower P-R-M aquifer.
	tions people: / / or o	To work tap the fewer Y X III aquiler.
7) Gloucester City-G	loucester City obtains the	neir drinking water from 2 wells and 2 back-up wells.
Both wells in use pum	p at approximately the :	same level. All 4 wells (those in constant use and the
two back-ups) are loc	ated in the 2-3 mile ring	and the total service population is 12,400 people.
All wells are considere	ed to tap the lower P-R-I	vi aquifer.
8) Camden-Camden	obtains their drinking w	ater from public supply wells. All of the wells are
located outside of 4 m	niles from the site.	
9) Mt. Ephraim, Had	don Height, Vorhees-T	hey obtain their drinking water from the N.J. American
Water Co. N.J. Ameri	can Water Co. operates	45 wells which serve approximately 215,000 people.
Altogether, 15 of their	wells are located within	4 miles of the site, with 2 wells located in
the 1/2-1 mile ring, 8	wells located in the 1-2	mile ring, and 5 wells located in the 2-3 mile
ring. All of the wells a		Time ting, and o wells located in the 2-0 time
	are considered to tap the	
215,000/45 = 4,778 p		
215,000/45 = 4,778 p		e lower P-R-M aquifer.
	eople per well.	e lower P-R-M aquifer.
1/2-1 mile ring	eople per well. 2 X 4,778 = 9,556 pe	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring 2-3 mile ring	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring 2-3 mile ring Summary	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p 5 X 4,778 = 23,890 p	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring 2-3 mile ring Summary 0-1/4 mile ring	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p 5 X 4,778 = 23,890 p 0 people 0 people	e lower P-R-M aquifer. ople eople
1/2-1 mile ring 1-2 mile ring 2-3 mile ring Summary 0-1/4 mile ring 1/4-1/2 mile ring	eople per well. 2 X 4,778 = 9,556 pe 8 X 4,778 = 38,224 p 5 X 4,778 = 23,890 p 0 people 0 people	e lower P-R-M aquifer. ople eople eople 17 people using lower P-R-M

To: File	Date: August 10, 1992
From: Lisa Szegedi	Project #: 8003-080
Subject: Drinking Water S	
(con't)	
2-3 mile ring 2,520 +7	7,000 + 6,000 + 23,890 = 39,410 using the lower P-R-M
3-4 mile ring 15,000 +	- 11,515 = 26,515 people using the lower P-R-M
	· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·	·
·	

008-C

Flace File No. <u>8003 - 0</u>		PHONE CONVERSATI	ION/AGKEE	MENT.	Ç.
Date: 6 August			0 59	_ MAM	[] PM
[] Incoming Call	From:				
	Affiliation:			Telep	phone No.
Outgoing Call		Park Huff		09-931-	
	Affiliation:	Bellmaur Wat	ER DODT., A	SST. SUPER	INTEND
Malcolm Pirnie Staff: (Receiving or Calling)			· -	Tele	phone No.
Summary of Co	nversation	[] Agreement:			
MR. HUFF LOS	CATED THE	4 wells for	HE BRUM	AUR TWP	AS
	· Zwelle	- LEAF ALE	WE BOLT	AE - 10	DOO GIPM
		TREATMENT	PLANT)	DOD GPM	
	· 2 wells	- WARRELL	CARTER	le .	
		#8 = 800GPM	#6=1	000 GPM	
· Wells DENL	ING FROM	POTOMIC! PARITA	A AQUIA	<u>و</u>	
· CURRELITEY	SUPPLYLING	APPROXIMATELY	5522	PERSONS	
			· · · · · · · · · · · · · · · · · · ·		
		· · · · · · · · · · · · · · · · · · ·		······································	
			 		
				<u> </u>	
			· · · · · · · · · · · · · · · · · · ·		
· · · · · · · · · · · · · · · · · · ·					
f:\rectele.jan(1)				· · · · · · · · · · · · · · · · · · ·	

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

August 25, 1992

Time: 9:00 AM [] PM []

Outgoing Call

To:

Tony Sansone

(609)-931-5721

Telephone No.

Affiliation:

Bellmawr Water Dept.

Malcolm Pirnie Staff: Lisa Szegedi

Telephone No.

Summary of Conversation:

Both wells located at Leaf Ave./Belt Ave. tap the lower Potomac-Raritan aguifer, while both wells located at Warren Ave./Carter Ave. tap the middle Potomac/Raritan aquifer.

Ollerc

File No. <u>8003 - 08</u>	3-0			* 💉
Date: 7 AUGUST	1992.	Time: 9.5	54 N	AM [] PM
[] Incoming Call	From:			
A	Affiliation:			Telephone No.
Outgoing Call	_	BILL PACKER		G-7785 Telephone No.
		DUPERINTENDANT, W	ater dist.	ROOKLAWAI
Malcolm Pirnie Staff:_ (Receiving or Calling)	KKKEY Name	KAMPFER	609-8	160-0100 Telephone No.
Summary of Con	versation	[] Agreement:		
MR PACKER IN	FORMED	ME OF THE FOLLOW IN	G LOCATIONS	s for
Wells IN L	Sestvill	= / BROOKLAWN		
	114 CROV	UNI POINT RO		
5 - 1	INE ST.	I CROWN PAINT Rd.		
U)ells Den	FROM B	ue Potomic - Raritan - M	100mHU 84.0	ARE
300 - 3SO	foet peep	AUG. PIMPAGE	800 - 1000	GPM
LURRENTY SUP	PLYING !	APPROV 7000 GUST I	PERSONS	<i></i>
BROOKLAWN				
	4/Town G	ZUTEL.		
	Blue /	Ion lessey Rd.	· · · · · · · · · · · · · · · · · · ·	
		400 GPM I ARE AP	PROX 300-59	SO LEET
DECP DRAW	ING FROM	RARITAN- POTOMIC-		
· CURRENTLY	PERUICE	2520 PERSONS		_
			·	
				
				
				
f:\rectele.ian(1)				

09-C

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

August 28, 1992

Time: 9:57 AM PM []

Outgoing Call

. To:

Bill Packer

(609)-456-7785

Telephone No.

Affiliation:

Westville/Brooklawn Water District

Malcolm Pirnie Staff: Lisa Szegedi

(609) 860-0100

Telephone No.

Summary of Conversation:

All of the wells in Brooklawn tap the lower P-M-R aquifer. Wells #4 and #6 in Westville also tap the lower P-M-R aquifer. Well #5 in Westville in screened in both the upper and lower P-M-R.

015-C

400

File No. <u>8003-08</u>	<u>3-0</u>			`
Date: 7Aug. 1992	2	Time:	[]AM	[] PM
[] Incoming Call	From:			
A	Affiliation:		Tel	ephone No.
Outgoing Call	To: ED DEAK	(609)	848-020	<u> </u>
4	Affiliation: Superialve	Depte	ne Two Was	ephone No.
	RICKEY KAMPFE	.		
(Receiving or Calling)			Tel	lephone No.
DEPTFORD TWP	Versation [] Agreer CURPLUTUY OPER 2 ON-LINE SHORT	ATES 6 WELLS	, However V3). The Loc	WOLL ATIONS
weu #				PUMPAGE
	PRINCETON / OAK			900 GPM
	PRINCETON / HAVER		- , · · · · · · · · · · · · · · · · · · 	<u>900 Gen</u>
				850 GPM
	MITY HOUSE RA / IND			
<u>6 - 20</u>	TH VIEW / DELSEY	Deine (MAINDER	(ELE)	1000 GPM
/ - BA	UK BRIDGE BLUD (LA	UD O LLAKES DULPM	BUT)	1000Gpm
	SWESSOU DRIVE IJA		MODE)	1000 GPM
* NO OPERATION	AL DIS OF THIS PER	LIDD		
· ALL DRAW FROM	RARLTIAN - POTOMI	к-Месотну Д	aurte.	
CURPRITLY SE	RUKE APPROXIMATE	S COOPS KE	Regns	

			<u></u>	
				······································
f:\rectele.jan(1)				

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

August 28, 1992

Time: 10:08 AM PM []

Outgoing Call

To:

Ed Deak

(609 -848-0200

Telephone No.

Affiliation:

Deptford Twp. Water Dept.

Malcolm Pirnie Staff: Lisa Szegedi

Susa begod

(609) 860-0100 Telephone No.

Summary of Conversation:

Mr. Deak does not know if the wells tap the upper, middle, or lower P-M-R aquifer, however all of the wells are drilled to a depth of approximately 400 feet, and they screen from 150 to 230 feet.

7.465 File No. <u>8003-0</u>	18-0	•	,
Date: 7 August	1992	Time: 8:21	[V]AM []PM
[] Incoming Call	From:		
	Affiliation:		Telephone No.
Outgoing Call			854-2332
	Affiliation: Superintens	DANT, COLLING	Telephone No.
Malcolm Pirnie Staff (Receiving or Calling	RICKEY KAMPFE	e_	Telephone No.
MR MYER LOC	ATED THE SEVEN WE 200 WATER DOPT.	ent: US OPERATED	BY THE
3 HILLС 4 South 1 5 Locate	POAD ALONG MEWIC REST GMAPLE PARK DRIVE AT END (AP DIN ROBERTS PARK	PROX LOF GARFIA	
6 H	11		· · · · · · · · · · · · · · · · · · ·
FROM THE	APPROXIMATELY 29 POTOMAC-PARITANI P 600-1000 GF	-MAGGTHY FO	emation Adulter.
Cuppently	BUPPCYING APPRO	z 21,000 per	sons
f:\rectele.jan(1)			

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

August 28, 1992

Time: 11:14 AM [Y PM []

Outgoing Call

To:

John Myer

(609)-854-2332

Telephone No.

Affiliation:

Collingswood Water Dept.

Malcolm Pirnie Staff: Lisa Szegedi

(609) 860-0100

Telephone No.

Summary of Conversation:

Mr. Myer does not have any specific information on which aquifer the wells tap (upper, middle, or lower), however in his opinion it is probable that all wells tap the lower P-R-M aquifer.

013 C

File No. <u>8003-</u> (<u> </u>		× .
Date: 7 Aug. 19	92	Time: 1030	_[\(\int AM \) PM
[] Incoming Call	From:		
	Affiliation:		Telephone No.
[] Outgoing Call	To: Joe KING	60	PUBLIC WORKS # 1742 000 - 129-1
	Affiliation: SUPERINTENDA	INT HADDWIFIELD	Two Water Det
Malcolm Pirnie Staff:	RICKEY KAMPFER	•	
(Receiving or Calling) Name		Telephone No.
	nversation [] Agreement		
Me KING LOCAT	ED THE 4 WELLS CUR		
		<u>Death</u>	
	PIELYLLMOD AVAILE	300	900 G.PM
<u>6 - L</u>	AKE ST. WESE COBUSTA	E)	@ 1440 GPM
	PUTER ST (FOOT OF WAL		1000 GPM
<u> 7 - 6</u>	WIFE ST. (FOOT OF WALK	DT ST.) - L	800 GPM
f:\rectele ian(1)			

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

September 2, 1992

Time: 1:45 AM [] PM R

Outgoing Call

To:

Maureen Lantier

(609)-429-4700 ext. 4

Telephone No.

Affiliation:

Haddonfield Twp. Water Dept.

Malcolm Pirnie Staff: Lisa Szegedi

Susa projecti

(609) 860-0100 Telephone No.

Summary of Conversation:

All 4 of the wells operated by the Haddonfield Water Dept. tap the lower P-R-M aquifer.

File No. <u>8003 -</u>	08-0				<
Date: 7 Augus	7 1992	Time: <u>9:3</u>	9	AM	[] PM
[] Incoming Call	From:				
	Affiliation:			Telep	hone No.
Outgoing Call	To: Tom K	AIN		456-	
	Affiliation: Superv	ISOR GLOUCH	ESTER C	Telep	phone No. TER Dept
Malcolm Pirnie Staff: (Receiving or Calling)	RICKEY KAM	PFER	609-	860 - C	phone No.
Summary of Co	nversation [] Agre	eement:		•	
MR CAIN IN	FORMED ME OF	4 wells Lo	CATED C)U	····
OF THE 4	BLUD ALL	USED THE	UDSON SI OTHER	r. Z <i>Ben</i> ud	<u> </u>
BACK-UI	S FOR EMERGEN	KJES			
WELL PUMP	AUG 1000 GPM	<u> Depth appe</u>	ex 200	REST	
CARCUTLY SE	PUICE 4.092 ACC	OUNTS ; APPR	ox 15.4	OO PERS	SONS
					
				-	
					·····
					······································
		- F		·	
f:\rectele ian(1)			_		



MALCOLM PIRNIE

MEMORANDUM

Date: August 27, 1992

To:

Lisa Szegedi, CNJ

From:

Gary C. Martin, P.E., DL

Re:

City of Camden Water Supply

Per our discussion, and subsequent discussion and review for release of information by Mr. Frederick H. Martin, Director of Utilities, City of Camden, I have compiled the information requested by your office. I have extracted the copied information from three sources: Engineering Report Water System Improvements, September, 1981; Study Report City of Camden Water System Improvement Study, Initial Draft, October, 1990; and Preliminary Design Camden Parkside Water Treatment Plant Improvements, October, 1989. Each of these references were prepared by Malcolm Pirnie as part of ongoing City of Camden Water System Efforts. On the attached copies, I have labeled the reports as Report 1, Report 2, and Report 3 respectively by putting a number in the upper left corner of the copies.

I have cleared the attached information through Mr. Martin. Any additional questions should be referred to either myself, or to Dominick Ruggiero in NNJ (Dominick has the originals and will be finalizing the <u>Water System Improvement Study</u>.

I believe your questions were as follows (the answers follow the questions):

 Location of all public water supply wells (either latitude and longitude, or street addresses, or locations on USGS Quad maps).

The attached maps detail the locations of the Morris, Delair, and Puchack Run wells. The Parkside wells are (for the purposes of your degree of accuracy, adjacent to the Parkside Plant.

• Whether each well is blended or is the sole supply to a particular service area.

All of the City wells are blended into the City system.

Service population for the individual or blended service areas.

The Population served by the City of Camden water system is 50,000 customers.

Aquifer and/or depth for each well.

This information is on the attached sheets.

- Pumpage values for each well.
 This information is on the attached sheets.
- Service area for the supply system.
 This information is on the attached sheets.
- c: City of Camden Tom Lane Dominick Ruggiero






TABLE 5-1

APPROXIMATE CAPACITIES AND PUMPAGE FROM EXISTING WELLS

System		Rated	Estimated Max.	Estimate	ed 1980 Product	ion (3)
and Well No.	Year Drilled	Capacity mgd(1)	Well Capacity mgd(2)		% Time In Operation	Avg. Pumping
Morris						
1	1944	1.44	1.7	0.7	< 5	0
3	1953	1.44	1.9	1.0	20	0.2
4	1960	2.02	2.5	1.4	20	0.3
6	1932	2.30	1.6	1.6	90	1.4
7	1932	2.30	2.5	1.6	90	1.4
8	1953	1.44	2.5	1.2	40	0.5
10	1960	2.02	2.5	1.3	70	0.9
11	1979	2.45	2.5	2.4	90	2.1
12	1980	2.38	2.5	2.4	0	0
13	1980	2.38	2.5	2.4	0	0
Delair	,					
1	1930	2.16	2.5	1.4	90	1.3
2	1930	1.87	1.3	0.9	90	0.8
3	1930	1.87	1.1	1.2	90	1.1
Sub-total	L ·	26.07	27.6	19.5		10.0
Puchack 1	Run				,	
1	1924	1.91	2.2	1.4	85	1.2
2	1924	1.93	1.3	0.7	85	0.6
3	1939	2.02	2.5	1.1	85	1.0
5	1930	1.44	2.5	1.2	90	1.1
7	1975	1.86	2.5	1.8	90	1.7
Sub-tota	1	9.16	11.0	6.2		5.6




TABLE 5-1 cont'd


APPROXIMATE CAPACITIES AND PUMPAGE FROM EXISTING WELLS


		D-4-3	Estimated Max.	Estimate	d 1980 Product	cion (3)
System and Well No.	Year Drilled	Rated Capacity mgd(1)	Well Capacity mgd(2)		% Time In Operation	Avg. Pumping
Parkside	·					
13	1953	1.44	1.1	1.1	20	0.2
17	1954	1.44	2.3	1.2	90	1.1
18	1976	1.83	2.0	1.7	90	1.6
Sub-total		4.71	5.3	4.0		2.9
Other Cit	y Sources					
4	1935	1.01	1.3	1.0	60	0.6
5	1963	1.01	1.7	1.0	60	0.6
7	1966	1.44	2.5	1.4	25	0.4
11	1942	1.44	2.0	1.1	70	0.8
Sub-tota	l	4.90	7.5	4.5		2.4
TOTAL		44.84	51.4	34.2		20.9


Notes:

- 1. Original "guaranteed" capacity of well and pump from City records.
- Theoretical capacity of well assuming no pump limitations and no interference from other wells. Based on well test records and generally-accepted maximum yields per well diameter.
- 3. Estimated from discussions with City personnel and review of City records.









NOTES


- I. BASED ON 1975 N PREPARED BY IN SERVICES OFFICI
- 2. MAINS 8-INCHES AND SMALLER A


CITY OF CAME DEPARTMENT OF U


> REPORT- 05 WATER SYSTI IMPROVEMEN


SKELETAL PLA WATER TRANSMI AND DISTRIBU SYSTEM

3 (5.









A

600






TABLE 4-1

DELAIRE WELL FIELD

Owner Well No.	Date Drilled	Present Status 5.P.	Total Depth	Well Diameter (in)	Pump Setting C.B.	Pump HP/Stages	Column Pipe Diameter (in)	Bowl Diameter (In)		Pumping Test Date	Static Water Level From T.O.C (ft)	Average Prod. (gpm)	Pumping Water Level from T.O.C. (ft)	Specific Capacity (gpm/h)	
1	1930		139'	26	110'2"	100/4	10	12	18	19 6 0 1989	10 35	1680 1133	41 49		Drouse Ave
2	1930	0/\$	146'	26	114'4"	75/3	10	12	18	1960 1989	13 25'1*	1330 725	88 93'7"	10.5	pH=6.0
3	1930	O/S	128'6"	26	89'4"	100/3	10	12	18	1960 1989	11'5″ 26	1850 739	44'3 " 89		Before 89 Rehab 150gpm pH=6.75

Abbreviations: O/S - out of service

S.P. - Samuel Pine, Well-Field Superintendent

T.O.C - Top of Casing C.B. - Center Line of Bowl



TABLE 4-2

MORRIS - SOUTHFIELD

Owner Well No.	Date Drilled	Present Status S.P.	Total Depth	Well Diameter (in)	Pump Setting C.B.	Pump HP/Stages	Column Pipe Diameter (in)	Bowl Diameter (in)	Well Screen Diameter (in)	Pumping Test Date	Static Water Level From T.O.C (ft)		Pumping Water Level from T.O.C. (ff)	Specific Capacity (gpm/ft)	Comments
	A					in a colar goo		XV.				(gpm)	1 117	877151113	Comments
7N	1932	Good	120'	14	89'6"	60/3	8	12	14	1989	30	1278	83	24	
8	1955	Good	124'	18'	94'1"	50/3	10	12		1989	32	600	92	10.7	Debris, High Iron
9N	1932	O/S	143'	18	114'	50/3	10	12		1985 1986 1987	38	775 653 742	119 114 105		Column pipe Dropped 1988
. ₁ 10	1961	Good	19'5	18	94'7"	60/3	10	12		1961 1989	19 36	1529 1272	46 103 、	18.9	
11	1979	Good	48'10	18	99'11"	100/4	10	12		1979 1989	39 41	2030 1130	85'7 " 97	20.1	Reverse ro- tary, debris pH =6.55
12	1980	Good	124'	18x16	84'9"	75/4	10	12		1980 1989	32 35	2030 1473	70 86'10"	28.8	
13	1981	Good		18x16	84'9″	75/4	10	12		1981 1989	34'7 " 35	1515 1543	63 89	28.5	pH=6.84

Abbreviations: O/S - out of service

S.P. - Samuel Pine, Well-Field Superintendent

T.O.C - Top of Casing

C.B. - Center Line of Bowl



TABLE 4-2 Con't

MORRIS - NORTHFIELD

Owner Well No.	Date Drilled	Present Status S.P.	Total Depth	Well Diameter (in)	Pump Setting C.B.	Pump HP/Stages	Column Pipe Diameter (in)	Bowl Diameter (in)		Pumping Test Date	Static Water Level From T.O.C (it)	Average Prod. (gpm)	Pumping Water Level fromTOC (ft)	Specific Capacity (gpm/ft)	Comments
1A		Site Flooded, O/S 5 yrs	121'	18	99'7*	50/3	10	12		1944 1961	10	1125 1110	81		Needs Discharge Pipe & Powe
2A		Site Flooded, O/S 10yrs	27'6	18	89'7"	50/3	10	12		1941 1961	12 9'6"	1555 818	87		Motor Miss- ing,building collapsed
3A	1953	Good	103'	18	78'10"	50/2	10	12		1953 1989	12 32	1127 1096	86	1	Debris, Junk truck, scat- tered pipes, pH=6.45
4A	1961	Good	34'5	18	99'4"	Trimmed 60/3	10	12		1961 1989	12 24	1585 1641	41 78	30.3	Extensive dumping, pH=6.65
5	Building Demolished – dishcharge pipe broken. Estimate leak at 500 – 700 gpm. +/- 6 Acres underwater														
6N	1932	O/S Good	33'6	18	103'9″	50/2	8	12		1932 1989	33	1550 500	65 102		Pumping gravel,1987- new screen No improv.

Abbreviations: O/S - out of service

S.P. - Samuel Pine, Well-Field Superintendent

T.O.C - Top of Casing

C.B. - Center Line of Bowl

134649 **EXPLANATION** MONTGOM Quaternary alluvium probably underlainin part by Magothy and Raritan formations DELAIRE WELLFIELD Cohansey Sand **PUCHACK WELL FIELD** Kirkwood Sand Mount Laurel and CRETACIOU Wenonah sands Englishtown sand Magothy and Raritan formations Crystalline rocks which contain little water

SOURCE: BULLETIN 39 N.J. DEPT. OF CONSERVATION AND DEVELOPMENT 1932


MALCOLM PIRNIE


CITY OF CAMDEN WATER SYSTEM IMPROVEMENTS

MAP OF CAMDEN AREA SHOWING PRINCIPAL WATER-BEARING FORMATIONS AND LOCATION OF SOURCES OF PUBLIC WATER SUPPLIES

MALCOLM PIRNIE, INC.

FIGURE 4-2





POTENTIOMETRIC DECLINE MAP FOR THE POTOMAC-RARITAN-MAGOTHY AQUIFER SYSTEM IN CAMDEN COUNTY, 1900-68

FIGURE 4-4






TABLE 5-3

Morris Delair Finished Water Quality Monthly Averages

	Treated				Pre	Post			Free CI2		
	Flow		Alk	Hardness	Cl2	C12	Lime	PO4	Resid	Iron	Мп
Date	(mgd)	ρH	(mg/L)	(mg/L)	(lbs)	(lbs)	(lbs)	(lbs)	(mg/L)	(mg/L)	(mg/L)
1/89	13.00	6.93		·	200.00	200.00	6194.13	100.00	0.17	0.10	
2/89	12.54	9.05				400.00	6300.00	100.00	0.18	0.18	0.05
3/89	13.19	9.05	76.00	156.00		400.00	6785.00	40.00	0.16	0.20	0.07
4/89	15.27	8.80				400.00	4605.00	96.00	0.22	0.38	0.11
5/89	15.93	9.01				400.00	3214.00	100.00	0.24	0.38	0.12
6/89	17.91	9.34				405.00	4660.00	100.00	0.30	0.34	0.07
7/89	16.73	9.35	92.00	89.10		500.00	4360.00	100.00	0.39	0.27	0.06
8/89	16.83	9.32				500.00	3889.00	100.00	0.42	0.25	0.07
9/89	15.05	8.85				500.00	3403.00	100.00	0.39	0.30	0.11
10/89	16.01	9.35			;	500.00	3366.00	100.00	0.35	0.29	0.06
11/89	14.57	9.45				427.00	3393.00	73.00	0.33	0.29	0.06
12/89	14.13	9.40	54.00	71.00		350.00	3488.00	97.80	0.33	0.28	0.10
1/90	15.40	9.39				343.00	4187.00	52.00	0.33	0.25	0.06
2/90	1.95	9.47				423.00	6187.00	50.00	0.31	0.23	0.06

TABLE 2-2

WELL CONSTRUCTION AND PERFORMANCE DATA

Component	Well	Well	Well
	<u>No. 13</u>	<u>No. 17</u>	<u>No. 18</u>
Year Drilled Depth (feet) Pump Setting Depth (feet) Casing Dimension (in x in) Yield Original (gpm) Current Pumping Level	1954 230 173 10x14 963 158	1954 257 183 16x18 1001 188	1978 288 180 18 ⁽¹⁾ 1300

Notes:

1- Diameter of the well = 18 inches



TABLE 2-1

WELL INSPECTION DATA

Component	Well	Well	Well
	<u>No. 13</u>	<u>No. 17</u>	<u>No. 18</u>
Pump Motor H.P. RPM Pressure Valve Check Valve Flow Meter Pressure Sensor Water Level Indicator Low Water Cut Well House Heater Emergency Power Supply	Layne U.S.Motor 75 1800 Yes Yes Yes No Yes No Good Yes No	Layne U.S.Motor 75 1800 Yes Yes Yes No Yes No Good Yes No	Layne U.S.Motor 75 1800 Yes Yes No Yes No Yes No Good Yes

Additional Comments:

- Flow meters for each well are located in the filter plant.
- New heaters were recently placed at the well houses.
- Emergency power supply is available but is not connected to the system.
- Pumps can be either operated manually at the wells or remotely from the plant.



TABLE 2-1 PROJECTED AVERAGE DAY WATER DEMANDS (mgd)

Year	Domestic	Domestic Equivalent	10-hour Industrial	24-hour Industrial	Other Demands	Total
1990	3.4	1.6	2.5	1.7	4.7	13.9
1992	3.7	1.6	3.0	1.8	4.9	15.0
1994	3.9	1.6	3.2	1.9	5.0	15.6
1995	4.3	1.6	3.3	1.9	5.1	16.2
2000	5.0	1.9	3.9	2.2	5.4	18.4
2005	5.9	2.2	4.5	2.6	5.7	20.9
2010	6.9	2.6	5.3	3.1	6.0	23.9

Notes:

- (1) Projections do not include usage by NJ American Water.
- (2) Domestic Equivalent includes institutions (schools, hospitals, etc.)
- (3) 10-hour Industrial includes industrial sites having 10-hr work days as well as small businesses and office complexes.
- (4) 24-hour Industrial includes industrial sites that operate 24 hours a day.
- (5) Other demands include leakage and unmetered flow. Unmetered flow includes fireflow, main flushing, swimming pools, water testing, construction sites, sewer cleaning, street cleaning, general landscaping, etc...
- (6) 1990 average day water demands are based on actual usage as measured in the field.

024-0

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No.

8003-080

Date:

September 4, 1992

Time: 11:00 AM | PM |

Outgoing Call

To:

J.P. Duganzic, P.E.

(609)-547-1700

Telephone No.

Affiliation:

N.J. American Water Company

Malcolm Pirnie Staff: Lisa Szegedi

(609) 860-0100

Telephone No.

Summary of Conversation:

Mr. Duganzic verified the locatins of the wells which are located on the SI 4- mile radius map. The locations are the following:

- 1) 6 wells are located near the 7th Ave. and Rt. 295 in Haddon Heights
- 2) 2 wells are located near Walnut Ave. in Magnolia
- 3) 3 wells are located near 7th Ave. and Chews Landing Road in Runnemede
- 4) 2 wells are located near Park Ave. in Mt. Ephraim
- 5) 2 wells are located near the intersection of Clements Bridge Road and Black Horse Tpke. in Runnemede. (Note: On the SI map one well is located on the east side of Black Horse Tpke. and one well is located on the west side of Black Horse Tpke. Both wells are located to the east of Black Horse Tpke.)

Altogether, this system contains 45 wells which serve approximately 215,000 people. The water from all of the wells is blended before distribution. Not all wells are in use at all times. Depending upon the demand, wells are turned on and off throughout the year. All of the wells tap the P-R-M aquifer, with approximately 1/2 the wells tapping the lower P-R-M, 1/3 of the wells utilizing the middle P-R-M, and 1/6 of the wells screening the upper P-R-M. Mr. Duganzic confirmed the presence of a continuous layer of clay approximately 100 feet thick in the vicinity of the site all the way south to Atlantic City.

ARCS II CONTRACT 68-W9-0051

1 -	73
001	-(-)
الركان	

FLAGS

MALCOLM PIRNIE, INC.
RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No. <u>8003 -</u> C	18-0				<u>`</u>
Date: 6 AUGUST	1992	_	Time: 1054	L[VAM	[] PM
[] Incoming Call	From:_				
	Affiliation:	·	·	Tele	phone No.
Outgoing Call			ARTHAL		
			COUTS, MOU	UT EPHPAN	phone No.
Malcolm Pirnie Staff:		4 KAMPFER	<u>.</u>		
(Receiving or Calling)	-			I ele	phone No.
Summary of Co				и U 500 ~	
IN THE MOU	UT EPHR	LAM TUP.	are being 5	UPPLIED WITH	<u>ksous</u>
POTABLE DE	HEING L	UATER .			
May Enua	1110 00		AD 450	F004	
MOUNT EPHRI MEN JERSEN	THE REGICEN	LIDATES C	OP IIS WAT	ANT HALL DA	
OF ITS OWN	TWP. U	CLS.		MOI PEACE PAR	<u> </u>
					· · · · · · · · · · · · · · · · · · ·
			· · · · · · · · · · · · · · · · · · ·		·
				-	
					
		<u> </u>			
					
					
					
					
	-				
					·
				······································	
f:\rectele ian(1)					

010-C

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No. 8003-08	3-0			×
Date: 7 AG92		Time: 9	:13	AM []PM
[] Incoming Call	From:			
A	Affiliation:			Telephone No.
[YOutgoing Call	To: 1/4 4	OUNG	5	47-3327
A	Affiliation: Superia	JEUDANT, HAD	mu Heigh	Telephone No.
Malcolm Pirnie Staff:_/ (Receiving or Calling) l	RICKEY KAMP	FER	7.00	Telephone No.
Summary of [/Conv	versation [] Ag	reement:		
MR YOUNG INF OF ITS PUBLIC AMBRICAN WATE OF ITS OWN W	POTABLE WATER ON A	ER SUPPLIES 1	FROM THE	NEW JERSEY
	<u> </u>			
				•
· · · · · · · · · · · · · · · · · · ·				
f:\rectele.jan(1)				

011-0

ARCS II CONTRACT 68-W9-0051 MALCOLM PIRNIE, INC. RECORD OF TELEPHONE CONVERSATION/AGREEMENT

File No. <u>8003-0</u>	8-0			~
Date: 7 Aug. 9	2	Time: 93	[]AM	[] PM
[] Incoming Call	From:			
	Affiliation:		Te	lephone No.
Outgoing Call	TO: DIDALA	CRUZ	609-428-	5914
	Affiliation: CLERK		- TT	
Malcolm Pirnie Staff:_ (Receiving or Calling)	Name		609-8 2 Te	<u>O -0100</u> lephone No.
Summary of [Con	nversation [] Agr	eement:		
MS CRUZ STAT	o by McW Jeg Of Vothes do	SEU AMERICAN	WATER CO	MO
			·	
				······································
				
		· ·		· · · · · · · · · · · · · · · · · · ·
		,		
		 		
		<u>.</u>		
				
	to the second se	- 	W	
f:\rectele.jan(1)				

ΜΔΙ	COL	M	PIR	NIF.	INC.
****					HU.

PROJECT NOTES

To: File	Date: April 1, 1993
From: Lisa Szegedi	Project #: 8003-080
Subject: Waste Source	Site Name: Flags, Inc.

One waste source has been identified at the Flags, Inc. site. Based on soil sampling results, an area of 26,000 square feet of soil contaminated with organic and inorganic contaminants has been identified.

PREscore 1.0 - PRESCORE.TCL File 12/23/91 HRS DOCUMENTATION RECORD Flags Incorporated - 09/19/92

1. Site Name: Flags Incorporated (as entered in CERCLIS)

2. Site CERCLIS Number: NJD 002352300

3. Site Reviewer: Lisa Szegedi/Steven T. McNulty

4. Date: 9/9/92

 Site Location: Bellmawr/Camden, New Jersey (City/County, State)

6. Congressional District: NJ-01

7. Site Coordinates: Single

Latitude: 39 52'09.0" Longitude: 075 04'55.0"

	Score
Ground Water Migration Pathway Score (Sgw)	19.88
Surface Water Migration Pathway Score (Ssw)	0.21
Soil Exposure Pathway Score (Ss)	12.86
Air Migration Pathway Score (Sa)	0.48
Air Migration Pathway Score (Sa)	0.48

Site Score	11.84
:	

NOTE

EPA uses the terms "facility," "site," and "release" interchangeably. The term "facility" is broadly defined in CERCLA to include any area where hazardous substances have "come to be located" (CERCLA Section 109(9)), and the listing process is not intended to define or reflect boundaries of such facilities or releases. Site names, and references to specific parcels or properties, are provided for general identification purposes only. Knowledge regarding the extent of sites will be refined as more information is developed during the RI/FS and even during implementation of the remedy.

PAGE:

1

PAGE:

PRESCORE 1.0 - PRESCORE.TCL File 12/23/91 GROUND WATER MIGRATION PATHWAY SCORESHEET Flags Incorporated - 09/19/92

GROUND WATER MIGRATION PATHWAY Factor Categories & Factors	Maximum Value	Value Assigned
Likelihood of Release to an Aquifer Aquifer: Lower Aquifer PMR Sy	, !	
1. Observed Release	550	0
2. Potential to Release 2a. Containment 2b. Net Precipitation 2c. Depth to Aquifer 2d. Travel Time 2e. Potential to Release	10 10 5 35	10 6 1 5
[lines 2a(2b+2c+2d)] 3. Likelihood of Release	500 550	120 120
Waste Characteristics		
4. Toxicity/Mobility 5. Hazardous Waste Quantity 6. Waste Characteristics	* * 100	1.00E+02 10 6
Targets		
7. Nearest Well 8. Population	50	9.00E+00
8a. Level I Concentrations 8b. Level II Concentrations 8c. Potential Contamination 8d. Population (lines 8a+8b+8c) 9. Resources 10. Wellhead Protection Area 11. Targets (lines 7+8d+9+10) 12. Targets (including overlaying aquifers) 13. Aquifer Score	** ** ** 5 20 ** **	0.00E+00 0.00E+00 2.27E+03 2.27E+03 0.00E+00 0.00E+00 2.28E+03 2.28E+03 19.88
GROUND WATER MIGRATION PATHWAY SCORE (Sgw)	100	19.88

^{*} Maximum value applies to waste characteristics category. ** Maximum value not applicable.

SURFACE WATER OVERLAND/FLOOD MIGRATION COMPONENT Factor Categories & Factors DRINKING WATER THREAT	Maximum Value	Value Assigned
Likelihood of Release		
1. Observed Release 2. Potential to Release by Overland Flow	550	0
2a. Containment 2b. Runoff 2c. Distance to Surface Water 2d. Potential to Release by Overland Flow [lines 2a(2b+2c)]	10 25 25 500	10 1 9 100
3. Potential to Release by Flood 3a. Containment (Flood) 3b. Flood Frequency 3c. Potential to Release by Flood (lines 3a x 3b)	10 50 500	10 7 70
4. Potential to Release (lines 2d+3c) 5. Likelihood of Release	500 550	170 170
Waste Characteristics		
6. Toxicity/Persistence 7. Hazardous Waste Quantity 8. Waste Characteristics	* * 100	1.00E+04 10 18
Targets		
9. Nearest Intake 10. Population	50	0.00E+00
10a. Level I Concentrations 10b. Level II Concentrations 10c. Potential Contamination 10d. Population (lines 10a+10b+10c) 11. Resources	** ** ** **	0.00E+00 0.00E+00 0.00E+00 0.00E+00 5.00E+00
12. Targets (lines 9+10d+11)	**	5.00E+00 5.00E+00
13. DRINKING WATER THREAT SCORE	100	0.19

^{*} Maximum value applies to waste characteristics category. ** Maximum value not applicable.

PREscore 1.0 - PRESCORE.TCL File 12/23/91 PAGE: SURFACE WATER OVERLAND/FLOOD MIGRATION COMPONENT SCORESHEET Flags Incorporated - 09/19/92

SURFACE WATER OVERLAND/FLOOD MIGRATION COMPONENT Factor Categories & Factors HUMAN FOOD CHAIN THREAT	Maximum Value	Value Assigned
Likelihood of Release		
14. Likelihood of Release (same as line 5)	550	170
Waste Characteristics		
15. Toxicity/Persistence/Bioaccumulation 16. Hazardous Waste Quantity 17. Waste Characteristics	* * 1000	5.00E+08 10 180
Targets		
18. Food Chain Individual 19. Population 19a. Level I Concentrations 19b. Level II Concentrations 19c. Pot. Human Food Chain Contamination 19d. Population (lines 19a+19b+19c) 20. Targets (lines 18+19d)	50 ** ** ** **	0.00E+00 0.00E+00 0.00E+00 3.00E-07 3.00E-07 3.00E-07
21. HUMAN FOOD CHAIN THREAT SCORE	100	0.00

^{*} Maximum value applies to waste characteristics category. ** Maximum value not applicable.

SURFACE WATER OVERLAND/FLOOD MIGRATION COMPONENT Factor Categories & Factors ENVIRONMENTAL THREAT	Maximum Value	Value Assigned
Likelihood of Release		
22. Likelihood of Release (same as line 5)	550	170
Waste Characteristics		
23. Ecosystem Toxicity/Persistence/Bioacc. 24. Hazardous Waste Quantity 25. Waste Characteristics	* * 1000	5.00E+06 10 56
Targets		
26. Sensitive Environments 26a. Level I Concentrations 26b. Level II Concentrations 26c. Potential Contamination 26d. Sensitive Environments (lines 26a+26b+26c) 27. Targets (line 26d)	** ** ** **	0.00E+00 0.00E+00 2.54E-01 2.54E-01 2.54E-01
28. ENVIRONMENTAL THREAT SCORE	60	0.03
29. WATERSHED SCORE	100	0.21
30. SW: OVERLAND/FLOOD COMPONENT SCORE (Sof)	100	0.21

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.

PRESCORE 1.0 - PRESCORE.TCL File 12/23/91 SOIL EXPOSURE PATHWAY SCORESHEET Flags Incorporated - 09/19/92

PAGE:

SOIL EXPOSURE PATHWAY Factor Categories & Factors RESIDENT POPULATION THREAT Maximum Value Value Assigned Likelihood of Exposure 550 1. Likelihood of Exposure Waste Characteristics Toxicity
 Hazardous Waste Quantity 1.00E+04 10 4. Waste Characteristics 100 18 Targets 5. Resident Individual6. Resident Population 4.50E+01 50 6a. Level I Concentrations ** 0.00E + 00** 6b. Level II Concentrations 5.70E+01 6c. Resident Population (lines 6a+6b) ** 5.70E+01 7. Workers 15 5.00E+00 8. Resources 0.00E + 009. Terrestrial Sensitive Environments *** 0.00E+0010. Targets (lines 5+6c+7+8+9) 1.07E+02 11. RESIDENT POPULATION THREAT SCORE 1.06E+06

^{*} Maximum value applies to waste characteristics category. ** Maximum value not applicable.

^{***} No specific maximum value applies, see HRS for details.

PAGE:

7

PRESCORE 1.0 - PRESCORE.TCL File 12/23/91 SOIL EXPOSURE PATHWAY SCORESHEET Flags Incorporated - 09/19/92

SOIL EXPOSURE PATHWAY Factor Categories & Factors NEARBY POPULATION THREAT	Maximum Value	Value Assigned
Likelihood of Exposure		
12. Attractiveness/Accessibility 13. Area of Contamination 14. Likelihood of Exposure	100 100 500	1.00E+01 2.00E+01 5.00E+00
Waste Characteristics		
15. Toxicity 16. Hazardous Waste Quantity 17. Waste Characteristics	* * 100	1.00E+04 10 18
Targets		
18. Nearby Individual 19. Population Within 1 Mile 20. Targets (lines 18+19)	1 ** **	0.00E+00 1.60E+01 1.60E+01
21. NEARBY POPULATION THREAT SCORE	**	1.44E+03
SOIL EXPOSURE PATHWAY SCORE (Ss)	100	12.86

^{*} Maximum value applies to waste characteristics category. ** Maximum value not applicable.

AIR MIGRATION PATHWAY Factor Categories & Factors	Maximum Value	Value Assigned
Likelihood of Release		
1. Observed Release 2. Potential to Release	550	0
2a. Gas Potential to Release 2b. Particulate Potential to Release 2c. Potential to Release 3. Likelihood of Release	500 500 500 550	0 280 280 280
Waste Characteristics		
4. Toxicity/Mobility 5. Hazardous Waste Quantity 6. Waste Characteristics	* * 100	8.00E-01 10 1
Targets		
7. Nearest Individual	50	2.00E+01
8. Population 8a. Level I Concentrations 8b. Level II Concentrations 8c. Potential Contamination 8d. Population (lines 8a+8b+8c) 9. Resources	** ** ** **	0.00E+00 0.00E+00 1.22E+02 1.22E+02 0.00E+00
10. Sensitive Environments 10a. Actual Contamination 10b. Potential Contamination 10c. Sens. Environments(lines 10a+10b) 11. Targets (lines 7+8d+9+10c)	*** *** ***	0.00E+00 1.35E-01 1.35E-01 1.42E+02
AIR MIGRATION PATHWAY SCORE (Sa)	100	4.82E-01

^{*} Maximum value applies to waste characteristics category.
** Maximum value not applicable.
*** No specific maximum value applies, see HRS for details.

PREscore 1.0 - PRESCORE.TCL File 12/23/91 WASTE QUANTITY Flags Incorporated - 09/19/92

PAGE:

9

1. WASTESTREAM QUANTITY SUMMARY TABLE, SOURCE: Contaminated Soil

a. Wastestream ID	
b. Hazardous Constituent Quantity (C) (lbs.)	0.00
c. Data Complete?	NO
d. Hazardous Wastestream Quantity (W) (lbs.)	0.00
e. Data Complete?	NO
f. Wastestream Quantity Value (W/5,000)	0.00E+00

PREscore 1.0 - PRESCORE.TCL File 12/23/91 WASTE QUANTITY Flags Incorporated - 09/19/92

PAGE: 10

2. SOURCE HAZARDOUS WASTE QUANTITY FACTOR TABLE

a. Source ID	Contaminated Soil
b. Source Type	Contaminated Soil
c. Secondary Source Type	N.A.
d. Source Volume (yd3) Source Area (ft2)	0.00 26000.00
e. Source Volume/Area Value	7.65E-01
f. Source Hazardous Constituent Quantity (HCQ) Value (sum of 1b)	0.00E+00
g. Data Complete?	NO
h. Source Hazardous Wastestream Quantity (WSQ) Value (sum of 1f)	0.00E+00
i. Data Complete?	NO
k. Source Hazardous Waste Quantity (HWQ) Value (2e, 2f, or 2h)	7.65E-01

Source Hazardous Substances	Depth Liquid (feet)	Concent.	Units
Barium Chromium Copper Lead Manganese Nickel Silver Zinc	< 2 NO	6.7E+01 2.8E+01 6.9E+02 1.1E+01 2.0E+02 3.4E+01 1.9E+02 2.1E+02	ppm ppm ppm ppm ppm ppm ppm ppm ppm